

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Matrix:

WATER

Fax: 908 789 8922

## **Report of Analysis**

Client: JACOBS Engineering Group, Inc. Date Collected: 06/04/25 15:50

Project: Former Schlumberger STC PTC Site D3868221 Date Received: 06/05/25

Client Sample ID: MW-19B-72-060425DL SDG No.: Q2234

Lab Sample ID: Q2234-07DL % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	43.1	D	20	3.80	12.0	mg/L		06/06/25 12:38	9056A
Sulfate	207	D	20	9.20	60.0	mg/L		06/06/25 12:38	9056A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits