

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 06/04/25 10:00 Project: PSEG 1500 Clinton St Date Received: 06/05/25 Client Sample ID: TP-3 SDG No.: Q2240 Lab Sample ID: Q2240-04 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	9.01	Н	1	0	0	pН		06/05/25 15:44	9045D
Ignitability	NO		1	0	0	oC		06/05/25 12:40	1030
Reactive Cyanide	0.0088	J	1	0.0084	0.050	mg/Kg	06/09/25 08:10	06/09/25 10:36	9012B
Reactive Sulfide	3.15	J	1	0.20	10.0	mg/Kg	06/09/25 15:30	06/10/25 08:22	9034

Comments: pH result reported at temperature 22.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits