

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 06/05/25 11:00 Project: PSEG 1500 Clinton St Date Received: 06/05/25 Client Sample ID: TP-1 SDG No.: Q2240 Lab Sample ID: Q2240-12 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.65	Н	1	0	0	pН		06/05/25 16:00	9045D
Ignitability	NO		1	0	0	oC		06/05/25 13:10	1030
Reactive Cyanide	0.013	J	1	0.0083	0.049	mg/Kg	06/09/25 08:10	06/09/25 10:36	9012B
Reactive Sulfide	6.34	J	1	0.20	10.0	mg/Kg	06/09/25 15:30	06/10/25 08:30	9034

Comments: pH result reported at temperature 27.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits