

Report of Analysis

Client:	VERINA CONSULTING GROUP, LLC	Date Collected:	06/05/25 11:00
Project:	Rotor Clip NJ WTD - 2025	Date Received:	06/05/25
Client Sample ID:	WATER-TREATMENT-DISCHARGE	SDG No.:	Q2243
Lab Sample ID:	Q2243-02	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.0046	J	1	0.00096	0.0050	mg/L	06/09/25 10:00	06/09/25 13:03	9012B
Oil and Grease	3.90	J	1	0.29	5.00	mg/L		06/09/25 13:00	1664A

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits