

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 06/06/25 12:18

Project: PSEG East Edison Test Pits Date Received: 06/06/25

Client Sample ID: TP11-MHL-WC SDG No.: Q2265

Lab Sample ID: Q2265-04 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.38	Н	1	0	0	pН		06/06/25 16:10	9045D
Ignitability	NO		1	0	0	oC		06/09/25 10:42	1030
Reactive Cyanide	0.050	U	1	0.0084	0.050	mg/Kg	06/09/25 08:10	06/09/25 10:43	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	06/09/25 15:30	06/10/25 08:50	9034

Comments: pH result reported at temperature 26.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits