

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 06/06/25 11:30

Project: PSEG Blair Road Sub Date Received: 06/06/25

Client Sample ID: WC-5 SDG No.: Q2266 Lab Sample ID: Q2266-08

> % Solid: 100

SOIL

Matrix:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.01	Н	1	0	0	pН		06/06/25 16:30	9045D
Ignitability	NO		1	0	0	oC		06/09/25 11:13	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	06/09/25 08:10	06/09/25 10:50	9012B
Reactive Sulfide	3.15	J	1	0.20	10.0	mg/Kg	06/09/25 15:30	06/10/25 08:56	9034

Comments: pH result reported at temperature 24.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits