

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PARSONS Engineering of New York, Inc. Date Collected: 06/05/25 10:40

Project: Con Ed Non MGP – Atlantic Ave 453957.600024.05 Date Received: 06/06/25

Client Sample ID: MW-5-20250605DL SDG No.: Q2268

Lab Sample ID: Q2268-02DL Matrix: WATER % Solid: 0

Parameter	Conc. (Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Sulfate	91.6	D	10 4.60	30.0	mg/L		06/09/25 15:09	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits