

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PARSONS Engineering of New York, Inc. Date Collected: 06/05/25 14:45

Project: Con Ed Non MGP – Atlantic Ave 453957.600024.05 Date Received: 06/06/25

Client Sample ID: MW-3-20250605 SDG No.: Q2268

Lab Sample ID: Q2268-08 Matrix: WATER

% Solid: 0

| Parameter | Conc. Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|------------|----|------|------------|-------|-----------|----------------|--------------|
| Sulfate | 14.1 | 1 | 0.46 | 3.00 | mg/L | | 06/09/25 13:22 | 300.0 |
| TDS | 538 | 1 | 1.00 | 10.0 | mg/L | | 06/09/25 12:30 | SM 2540 C-15 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits