## DATA OF KNOWN QUALITY CONFORMANCE/NON-CONFORMANCE SUMMARY QUESTIONNAIRE

Laboratory Name : Alliance Technical Group LLC Client : JACOB		JACOBS Engine	eering	Group	o, Inc.			
Project Location : Princeton Junction		Project Number :	D3868221					
Laboratory Sample ID(s): Q2275 Sampling Date(s): 6/08/2025								
List DI	SOP							
1	For each analytical method referenced in this la specified QA/QC performance criteria followed, explain any criteria falling outside of acceptable NJDEP Data of Known Quality performance sta	including the requirement to guidelines, as specified in the		<b>V</b>	Yes		No	
1A	Were the method specified handling, preservation, and holding time requirements met?				Yes		No	
1B	EPH Method: Was the EPH method conducted without significant modifications (see Section 11.3 of respective DKQ methods)				Yes		No	✓ N/A
2	Were all samples received by the laboratory in a condition consistent with that described on the associated chain-of-custody document(s)?			V	Yes		No	
3	Were samples received at an appropriate temper	erature (4±2° C)?		$\overline{\mathbf{A}}$	Yes		No	□ N/A
4	Were all QA/QC performance criteria specified standards achieved?	in the NJDEP DKQP			Yes	<b>V</b>	No	
5	a)Were reporting limits specified or referenced communicated to the laboratory prior to sample			V	Yes		No	
	b)Were these reporting limits met?			V	Yes		No	□ N/A
6	For each analytical method referenced in this la results reported for all constituents identified in presented in the DKQP documents and/or site-s	the method-specific analyte		$\overline{\mathbf{V}}$	Yes		No	
7	Are project-specific matrix spikes and/or laborate	tory duplicates included in this	s data set?	$\overline{\mathbf{A}}$	Yes		No	

Notes: For all questions to which the response was "No" (with the exception of question #7), additional information should be provided in an attached narrative. If the answer to question #1, #1A, or #1B is "No", the data package does not meet the requirements for "Data of Known Quality."

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Cover Page**

Order ID: Q2275

**Project ID:** Former Schlumberger STC PTC Site D3868221

**Client:** JACOBS Engineering Group, Inc.

## Lab Sample Number Client Sample Number

Q2275-01	OW-08B-72.5-060925
Q2275-02	OW-08B-72.5-060925-SIM
Q2275-03	EB01-060925
Q2275-04	EB01-060925-SIM
Q2275-05	TB01-060925

I certify that the data package is in compliance with the terms and conditions of the contract, both technically and for completeness, for other than the conditions detailed above. Release of the data contained in this hard copy data package has been authorized by the laboratory manager or his designee, as verified by the following signature.

Signature :			
Jighature .	——————————————————————————————————————	te:	6/23/2025

NYDOH CERTIFICATION NO - 11376

NJDEP CERTIFICATION NO - 20012