

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 06/10/25 09:52

Project: Sewaren Laydown Yard Date Received: 06/10/25

Client Sample ID: VNJ-210 SDG No.: Q2280
Lab Sample ID: Q2280-02 Matrix: SOIL

% Solid: 95.4

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.67	Н	1	0	0	pН		06/10/25 18:44	9045D
Ignitability	NO		1	0	0	oC		06/11/25 09:50	1030
Reactive Cyanide	0.0086	J	1	0.0083	0.049	mg/Kg	06/11/25 16:00	06/12/25 11:39	9012B
Reactive Sulfide	3.19	J	1	0.20	10.0	mg/Kg	06/12/25 11:30	06/12/25 16:49	9034

Comments: pH result reported at temperature 20.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits