

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900, Fax: 908 789 8922

Report of Analysis

Client: ATG-GREENVILLE AEC Date Collected: 06/10/25 Project: AEC-2025-0013-4017 Trumball Date Received: 06/11/25 Client Sample ID: SW-2 SDG No.: Q2292 Lab Sample ID: Q2292-02 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-50-8	Copper	10.2		1	1.89	10.0	ug/L	06/12/25 12:15	06/17/25 14:54	EPA 200.	7 E200.7
7439-92-1	Lead	1.92	J	1	1.21	6.00	ug/L	06/12/25 12:15	06/17/25 14:54	EPA 200.	7 E200.7
7440-66-6	Zinc	61.1		1	1.60	20.0	ug/L	06/12/25 12:15	06/17/25 14:54	EPA 200.	7 E200.7

Color Before: Colorless Clarity Before: Clear Texture: Color After: Colorless Clarity After: Clear Artifacts:

Metals ICP-Group1 Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range N =Spiked sample recovery not within control limits