

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Date Collected: 06/11/25 12:00

Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 06/11/25

Client Sample ID: WC-URBAN-FILL-C SDG No.: Q2301

Lab Sample ID: Q2301-02 Matrix: SOIL

% Solid: 83

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight) Prep Date	Date Ana.	Ana Met.
Oil and Grease	48.1		1	6.99	30.1	mg/Kg	06/13/25 09:30	SW9071B
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm	06/16/25 09:05	9095B
pН	8.13	Н	1	0	0	рН	06/12/25 17:10	9045D
TS	79.8		1	1.00	5.00	%	06/13/25 11:00	SM 2540 B-15
TVS	1.00	U	1	1.00	10.0	%	06/13/25 16:00	160.4

Comments: pH result reported at temperature 22.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits