

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 06/16/25 09:03 Project: Row Watchung Bridge Replacement Date Received: 06/16/25 Client Sample ID: WBR-2 SDG No.: Q2336 Lab Sample ID: Q2336-03 Matrix: SOIL % Solid: 82.5

Parameter	Conc.	Qua.	DF M	MDL LOQ/C	RQL Units	Prep Date	Date Ana.	Ana Met.
Paint Filter	1.00	U	1 1.	1.00 1.00	ml/100gm		06/18/25 10:30	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits