

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Lockwood, Kessler & Bartlett, Inc. Date Collected: 06/16/25 09:30 Project: Ansonia Landfill 2025 Date Received: 06/17/25 Client Sample ID: MW-1DL SDG No.: Q2344 Lab Sample ID: Q2344-01DL Matrix: WATER

% Solid: 0

Parameter	Conc. Qua	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	84.8 D	20 3.80	12.0	mg/L		06/18/25 11:58	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits