

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 06/18/25 12:26 Project: Secaucus HQ Date Received: 06/18/25 Client Sample ID: 3897 SDG No.: Q2355 Lab Sample ID: Q2355-02 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.20	Н	1	0	0	pН		06/19/25 14:37	9045D
Ignitability	NO		1	0	0	oC		06/20/25 09:02	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	06/23/25 09:10	06/23/25 11:52	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	06/24/25 13:50	06/24/25 16:09	9034

Comments: pH result reported at temperature 22.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits