

LAB CHRONICLE

OrderID: Q2364	OrderDate: 6/18/2025 4:07:57 PM
Client: G Environmental	Project: Ave B
Contact: Gary Landis	Location: D51,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2364-01	GAV1A	SOIL	PCB	8082A	06/18/25	06/20/25	06/20/25	06/18/25
Q2364-02	GAV1B	SOIL	PCB	8082A	06/18/25	06/20/25	06/20/25	06/18/25
Q2364-03	GAV2A	SOIL	PCB	8082A	06/18/25	06/20/25	06/20/25	06/18/25
Q2364-04	GAV2B	SOIL	PCB	8082A	06/18/25	06/20/25	06/20/25	06/18/25