

Hit Summary Sheet
SW-846

SDG No.: Q2390
Client: GFE LLC

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID:	SV1							
Q2390-01	SV1	Air	cis-1,2-Dichloroethene	29.3		3.93	19.8	ug/m3
Q2390-01	SV1	Air	Trichloroethene	209		1.29	1.61	ug/m3
Q2390-01	SV1	Air	Tetrachloroethene	10800	E	1.02	2.03	ug/m3
			Total Voc :	11100				
			Total Concentration:	11100				
Client ID:	SV1DL							
Q2390-01DL	SV1DL	Air	Trichloroethene	239	D	25.8	32.3	ug/m3
Q2390-01DL	SV1DL	Air	Tetrachloroethene	15600	D	20.3	40.7	ug/m3
			Total Voc :	15800				
			Total Concentration:	15800				



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	GFE LLC	Date Collected:	06/20/25
Project:	50 Jefferson Blvd, Staten Island NY	Date Received:	06/20/25
Client Sample ID:	SV1	SDG No.:	Q2390
Lab Sample ID:	Q2390-01	Matrix:	Air
Analytical Method:	TO-15	Test:	VOCMS Group2
Sample Wt/Vol:	400 Units: mL		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VL042666.D	10		06/23/25 11:30	VL062325

CAS Number	Parameter	Conc. ppbv	Conc. ug/M3	Qualifier	MDL	LOQ / CRQL	Units
TARGETS							
75-01-4	Vinyl Chloride	0.25	0.64	U	0.64	0.77	ug/m3
75-35-4	1,1-Dichloroethene	1.50	5.95	U	5.95	19.8	ug/m3
156-59-2	cis-1,2-Dichloroethene	7.40	29.3		3.93	19.8	ug/m3
71-55-6	1,1,1-Trichloroethane	0.16	0.87	U	0.87	1.64	ug/m3
79-01-6	Trichloroethene	38.8	209		1.29	1.61	ug/m3
127-18-4	Tetrachloroethene	1600	10800	E	1.02	2.03	ug/m3
SURROGATES							
460-00-4	1-Bromo-4-Fluorobenzene	10.4			65 - 135	104%	SPK: 10
INTERNAL STANDARDS							
74-97-5	Bromochloromethane	111000		2.79			
540-36-3	1,4-Difluorobenzene	286000		3.965			
3114-55-4	Chlorobenzene-d5	263000		8.888			

U = Not Detected

RL = Reporting Limit

MDL = Method Detection Limit

E = Value Exceeds Calibration Range

D = Dilution

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

Q = indicates LCS control criteria did not meet requirements

Report of Analysis

Client:	GFE LLC	Date Collected:	06/20/25
Project:	50 Jefferson Blvd, Staten Island NY	Date Received:	06/20/25
Client Sample ID:	SV1DL	SDG No.:	Q2390
Lab Sample ID:	Q2390-01DL	Matrix:	Air
Analytical Method:	TO-15	Test:	VOCMS Group2
Sample Wt/Vol:	400 Units: mL		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VL042667.D	200		06/23/25 12:27	VL062325

CAS Number	Parameter	Conc. ppbv	Conc. ug/M3	Qualifier	MDL	LOQ / CRQL	Units
TARGETS							
75-01-4	Vinyl Chloride	5.00	12.8	UD	12.8	15.3	ug/m3
75-35-4	1,1-Dichloroethene	30.0	119	UD	119	396	ug/m3
156-59-2	cis-1,2-Dichloroethene	19.8	78.5	UD	78.5	396	ug/m3
71-55-6	1,1,1-Trichloroethane	3.20	17.5	UD	17.5	32.7	ug/m3
79-01-6	Trichloroethene	44.4	239	D	25.8	32.3	ug/m3
127-18-4	Tetrachloroethene	2300	15600	D	20.3	40.7	ug/m3
SURROGATES							
460-00-4	1-Bromo-4-Fluorobenzene	10.2			65 - 135	102%	SPK: 10
INTERNAL STANDARDS							
74-97-5	Bromochloromethane	108000		2.787			
540-36-3	1,4-Difluorobenzene	283000		3.962			
3114-55-4	Chlorobenzene-d5	243000		8.888			

U = Not Detected

RL = Reporting Limit

MDL = Method Detection Limit

E = Value Exceeds Calibration Range

D = Dilution

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

Q = indicates LCS control criteria did not meet requirements



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

LAB CHRONICLE

OrderID:	Q2390	OrderDate:	6/20/2025 1:30:05 PM
Client:	GFE LLC	Project:	50 Jefferson Blvd, Staten Island NY
Contact:	Frank Galdun	Location:	D41,VOA Lab

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2390-01	SV1	Air	VOCMS Group2	TO-15	06/20/25		06/23/25	06/20/25
Q2390-01DL	SV1DL	Air	VOCMS Group2	TO-15	06/20/25		06/23/25	06/20/25