

Report of Analysis

Client:	Union Paving & Construction Company	Date Collected:	06/23/25 08:43
Project:	190 Park Ave Hanover Twp NJ - PO 2556-001	Date Received:	06/23/25
Client Sample ID:	PARK AVE -5	SDG No.:	Q2393
Lab Sample ID:	Q2393-09	Matrix:	SOIL
		% Solid:	91.3

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.21	J	1	0.044	0.26	mg/Kg	06/24/25 09:00	06/25/25 10:48	9012B
pH	9.46	H	1	0	0	pH		06/25/25 09:15	9045D

Comments: pH result reported at temperature 25.0 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits