

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 06/23/25 Project: Lawrenceville HQ Date Received: 06/23/25 Client Sample ID: Concrete-062325 SDG No.: Q2403 Lab Sample ID: Q2403-05 Matrix: SOIL % Solid: 97.4 Level (low/med): low

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units(Dry W	/eigh t)rep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	6.29	1 0.12	0.53	mg/Kg	06/25/25 10:25	06/27/25 13:49	6010D	SW3050

Color Before: Brown Clarity Before: Texture: Medium

Color After: Yellow Clarity After: Artifacts:

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits