

Report of Analysis

ſ	Client:	Tota	Total Quality Environmental Inc.							: 0	6/23/25		
	Project:		Flus	hing Av	ve					Date Received	: 0	6/23/25	
	Client Sa	mple ID:	1ST	-FL-CH	IILD	-CARE-M	IULTIPU	POSE-ROOM	-SINK-1	SDG No.:	Q	2404	
	Lab Sam	ple ID:	Q24	04-03						Matrix:	W	Vater	
	Level (lo	w/med):	low							% Solid:	0		
(Cas	Parameter	Conc.	Qua.	DF	MDL	I	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7	439-92-1	Lead	1.21	U	1	1.21		6.00	ug/L	06/25/25 14:50	06/27/25 14	:41 EPA 200.	7 E200.7

Color Before:	Colorless	Clarity Before:	Clear	Texture:	
Color After:	Colorless	Clarity After:	Clear	Artifacts:	
Comments: Metals Group4					
MDL = MethoLOD = Limit oD = Dilution	of Quantitation od Detection Limit	eet requirements	J = Estimated Value B = Analyte Found in Associated Method Blank * = indicates the duplicate analysis is not within control limits. E = Indicates the reported value is estimated because of the presence of interference. OR = Over Range N = Spiked sample recovery not within control limits		