

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Total Quality Environmental Inc. Date Collected: 06/23/25 Project: Date Received: 06/23/25 Flushing Ave Client Sample ID: 1ST-FL-HALLWAY-BATH-3RD-SINK-2 SDG No.: Q2404 Lab Sample ID: Q2404-10 Matrix: Water % Solid: Level (low/med): 0 low

Cas	Parameter	Conc.	Qua.	DF :	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	1.21	U	1 1	1.21	6.00	ug/L	06/25/25 14:50	06/27/25 15:21	EPA 200.	7 E200.7

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group4

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits