



A

B

C

SAMPLE DATA

Report of Analysis

Client:	Coppola Services	Date Collected:	06/24/25 09:04
Project:	Millville Sewage Treatment Plant - Field Sampling	Date Received:	06/24/25
Client Sample ID:	COP-SOIL-PILE	SDG No.:	Q2409
Lab Sample ID:	Q2409-02	Matrix:	SOIL
		% Solid:	96.4

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.80	H	1	0	0	pH		06/24/25 16:35	9045D
Ignitability	NO		1	0	0	oC		06/25/25 09:37	1030
Reactive Cyanide	0.010	J	1	0.0083	0.050	mg/Kg	06/25/25 10:45	06/25/25 12:56	9012B
Reactive Sulfide	3.16	J	1	0.20	10.0	mg/Kg	06/27/25 09:10	06/27/25 11:33	9034
TS	96.4		1	1.00	5.00	%		06/26/25 09:00	SM 2540 B-20
TVS	1.30	J	1	1.00	10.0	%		06/26/25 15:00	160.4

Comments: pH result reported at temperature 24.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	Q2409	OrderDate:	6/24/2025 2:11:50 PM
Client:	Coppola Services	Project:	Millville Sewage Treatment Plant - Field Sampling
Contact:	Jeffrey Simpkins	Location:	D51

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2409-02	COP-SOIL-PILE	SOIL			06/24/25 09:04			06/24/25
			Reactive Sulfide	9034		06/27/25	06/27/25 11:33	
			TS	SM2540 B			06/26/25 09:00	
			TVS	160.4			06/26/25 15:00	
			Corrosivity	9045D			06/24/25 16:35	
			Ignitability	1030			06/25/25 09:37	
			Reactive Cyanide	9012B		06/25/25	06/25/25 12:56	