



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: Coppola Services

SDG No.: Q2409

Project: Millville Sewage Treatment Plant - Field Sampling

RunNo.: LB136249

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Corrosivity	pH	7.00	7	100	90-110	06/24/2025
Sample ID: CCV1 Corrosivity	pH	2.01	2.00	101	90-110	06/24/2025
Sample ID: CCV2 Corrosivity	pH	12.02	12.00	100	90-110	06/24/2025

Initial and Continuing Calibration Verification

Client: Coppola Services	SDG No.: Q2409
Project: Millville Sewage Treatment Plant - Field Sampling	RunNo.: LB136261

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.098	0.099	99	85-115	06/25/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	06/25/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	06/25/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	06/25/2025