

LAB CHRONICLE

OrderID:	Q2413	OrderDate:	6/24/2025 3:05:00 PM
Client:	CDM Smith	Project:	South River WM Replacement
Contact:	Marcie Ann Encinas	Location:	D41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2413-01	TP-35	SOIL			06/23/25			06/24/25
			Diesel Range Organics	8015D		06/30/25	06/30/25	
			PCB	8082A		06/26/25	06/26/25	
			Pesticide-TCL	8081B		06/26/25	06/27/25	
			Gasoline Range Organics	8015D			06/26/25	
Q2413-02	TP-34	SOIL			06/23/25			06/24/25
			Diesel Range Organics	8015D		06/30/25	06/30/25	
			PCB	8082A		06/26/25	06/26/25	
			Pesticide-TCL	8081B		06/26/25	06/27/25	
			Gasoline Range Organics	8015D			06/26/25	
Q2413-03	TP-77	SOIL			06/23/25			06/24/25
			Diesel Range Organics	8015D		06/30/25	06/30/25	
			PCB	8082A		06/26/25	06/26/25	
			Pesticide-TCL	8081B		06/26/25	06/27/25	
			Gasoline Range Organics	8015D			06/26/25	
Q2413-04	TP-74	SOIL			06/23/25			06/24/25
			Diesel Range Organics	8015D		06/30/25	07/01/25	
			PCB	8082A		06/26/25	06/26/25	
			Pesticide-TCL	8081B		06/26/25	06/27/25	
			Gasoline Range Organics	8015D			06/26/25	
Q2413-05	TP-73	SOIL			06/23/25			06/24/25
			Diesel Range Organics	8015D		06/30/25	07/01/25	
			PCB	8082A		06/26/25	06/26/25	
			Pesticide-TCL	8081B		06/26/25	06/27/25	
			Gasoline Range Organics	8015D			06/26/25	
Q2413-06	TP-72	SOIL			06/24/25			06/24/25
			Diesel Range Organics	8015D		06/30/25	07/01/25	

LAB CHRONICLE

Gasoline Range Organics	8015D		06/26/25
PCB	8082A	06/26/25	06/26/25
Pesticide-TCL	8081B	06/26/25	06/27/25