

Duplicate Sample Summary

Client: Tully Environmental, Inc	SDG No.: Q2424
Project: Transfer Station-SPDES	Sample ID: LB136276BS
Client ID: LB136276BSD	Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Oil and Grease	mg/L	+/-18	16.9		17.0		1	0.59		06/26/2025