

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Tully Environmental, Inc Date Collected: 06/24/25 11:15 Project: Transfer Station-SPDES Date Received: 06/25/25 Client Sample ID: 001-WILLETS-PT-BLVD(MAY) SDG No.: Q2426 Lab Sample ID: Q2426-01 Matrix: WATER % Solid: 0

| Parameter | Conc. Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana.      | Ana Met.     |
|-----------|------------|--------|------------|-------|-----------|----------------|--------------|
| TSS       | 218        | 1 1.00 | 4.00       | mg/L  |           | 06/26/25 09:30 | SM 2540 D-20 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits