

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q2426
Project:	Transfer Station-SPDES	Sample ID:	Q2418-01
Client ID:	VAC-TRUCK-4074DUP	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	153		159		1	3.59		06/26/2025