

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Tully Environmental, Inc Date Collected: 06/24/25 Project: Transfer Station-SPDES Date Received: 06/25/25 Client Sample ID: 001-WILLETS-PT-BLVD(MAY) SDG No.: Q2426 Lab Sample ID: Q2426-01 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-89-6	Iron	7900	1 18.0	50.0	ug/L	06/25/25 14:50	06/25/25 19:04	EPA 200.7	7 E200.7

Color Before: Colorless Clarity Before: Cloudy Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group 12

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits