

Report of Analysis

Client:	GFE LLC	Date Collected:	06/25/25
Project:	135 W Jericito Trn Pk, Huntington NY	Date Received:	06/26/25
Client Sample ID:	SV1DL	SDG No.:	Q2432
Lab Sample ID:	Q2432-01DL	Matrix:	Air
Analytical Method:	TO-15	Test:	VOCMS Group2
Sample Wt/Vol:	400 Units: mL		

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VL042678.D	80		06/27/25 14:36	VL062725

CAS Number	Parameter	Conc. ppbv	Conc. ug/M3	Qualifier	MDL	LOQ / CRQL	Units
TARGETS							
75-01-4	Vinyl Chloride	2.00	5.11	UD	5.11	6.13	ug/m3
75-34-3	1,1-Dichloroethane	10.4	42.1	UD	42.1	162	ug/m3
156-59-2	cis-1,2-Dichloroethene	7.90	31.3	UD	31.3	159	ug/m3
71-55-6	1,1,1-Trichloroethane	1.30	7.09	UD	7.09	13.1	ug/m3
79-01-6	Trichloroethene	1.90	10.2	UD	10.2	12.9	ug/m3
127-18-4	Tetrachloroethene	880	5970	D	8.14	16.3	ug/m3
SURROGATES							
460-00-4	1-Bromo-4-Fluorobenzene	10.7			65 - 135	107%	SPK: 10
INTERNAL STANDARDS							
74-97-5	Bromochloromethane	112000			2.784		
540-36-3	1,4-Difluorobenzene	287000			3.952		
3114-55-4	Chlorobenzene-d5	253000			8.875		

U = Not Detected

RL = Reporting Limit

MDL = Method Detection Limit

E = Value Exceeds Calibration Range

D = Dilution

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

Q = indicates LCS control criteria did not meet requirements