

LAB CHRONICLE

OrderID:	Q2436	OrderDate:	6/26/2025 3:41:00 PM
Client:	CDM Smith	Project:	South River WM Replacement
Contact:	Marcie Ann Encinas	Location:	D51,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2436-01	TP-70	SOIL	SVOC-TCL BNA -20	8270E	06/25/25	06/27/25	06/30/25	06/26/25
Q2436-02	TP-69	SOIL	SVOC-TCL BNA -20	8270E	06/25/25	06/27/25	06/30/25	06/26/25
Q2436-03	TP-85	SOIL	SVOC-TCL BNA -20	8270E	06/25/25	06/27/25	07/01/25	06/26/25
Q2436-04	TP-86	SOIL	SVOC-TCL BNA -20	8270E	06/25/25	06/27/25	06/30/25	06/26/25
Q2436-05	TP-84	SOIL	SVOC-TCL BNA -20	8270E	06/25/25	06/27/25	06/30/25	06/26/25
Q2436-06	TP-83	SOIL	SVOC-TCL BNA -20	8270E	06/25/25	06/27/25	06/30/25	06/26/25
Q2436-07	TP-87	SOIL	SVOC-TCL BNA -20	8270E	06/26/25	06/27/25	06/30/25	06/26/25
Q2436-08	TP-100	SOIL	SVOC-TCL BNA -20	8270E	06/26/25	06/27/25	06/30/25	06/26/25
Q2436-09	TP-99	SOIL	SVOC-TCL BNA -20	8270E	06/26/25	06/27/25	06/30/25	06/26/25
Q2436-10	TP-82	SOIL	SVOC-TCL BNA -20	8270E	06/26/25	06/27/25	06/30/25	06/26/25