

LAB CHRONICLE

OrderID:	Q2458	OrderDate:	6/27/2025 4:22:00 PM
Client:	CDM Smith	Project:	South River WM Replacement
Contact:	Marcie Ann Encinas	Location:	D51,VOA Ref. #2 Soil,VOA Ref. #3 Water

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2458-01	TP-76	SOIL			06/26/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-02	TP-55	SOIL			06/26/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-03	TP-68	SOIL			06/27/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-04	TP-67	SOIL			06/27/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-05	TP-66	SOIL			06/27/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-06	TP-60	SOIL			06/27/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-07	TP-62	SOIL			06/27/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-08	TP-63	SOIL			06/27/25			06/27/25
			Mercury	7471B		07/01/25	07/02/25	
			Metals ICP-TAL	6010D		07/01/25	07/03/25	
Q2458-09	TP-59	SOIL			06/27/25			06/27/25

LAB CHRONICLE

Q2458-10	FB-06272025	Water	Mercury	7471B		07/01/25	07/02/25	06/27/25	06/27/25
			Metals ICP-TAL	6010D		07/01/25	07/03/25		
			Mercury	7470A		07/01/25	07/01/25		
			Metals ICP-TAL	6010D		07/01/25	07/03/25		
