

LAB CHRONICLE

OrderID:	Q2458	OrderDate:	6/27/2025 4:22:00 PM
Client:	CDM Smith	Project:	South River WM Replacement
Contact:	Marcie Ann Encinas	Location:	D51,VOA Ref. #2 Soil,VOA Ref. #3 Water

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2458-01	TP-76	SOIL	SVOC-TCL BNA -20	8270E	06/26/25	07/01/25	07/02/25	06/27/25
Q2458-02	TP-55	SOIL	SVOC-TCL BNA -20	8270E	06/26/25	07/01/25	07/02/25	06/27/25
Q2458-03	TP-68	SOIL	SVOC-TCL BNA -20	8270E	06/27/25	07/01/25	07/02/25	06/27/25
Q2458-04	TP-67	SOIL	SVOC-TCL BNA -20	8270E	06/27/25	07/01/25	07/02/25	06/27/25
Q2458-05	TP-66	SOIL	SVOC-TCL BNA -20	8270E	06/27/25	07/01/25	07/02/25	06/27/25
Q2458-06	TP-60	SOIL	SVOC-TCL BNA -20	8270E	06/27/25	07/01/25	07/01/25	06/27/25
Q2458-07	TP-62	SOIL	SVOC-TCL BNA -20	8270E	06/27/25	07/01/25	07/01/25	06/27/25
Q2458-08	TP-63	SOIL	SVOC-TCL BNA -20	8270E	06/27/25	07/01/25	07/01/25	06/27/25
Q2458-09	TP-59	SOIL	SVOC-TCL BNA -20	8270E	06/27/25	07/01/25	07/02/25	06/27/25
Q2458-10	FB-06272025	Water	SVOC-TCL BNA -20	8270E	06/27/25	07/03/25	07/03/25	06/27/25