

PIT#4

Client Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: JPCL Engineering Date Collected: 07/01/25 08:50

Project: NOHO RFI No. SC64025 NYC Date Received: 07/01/25

Lab Sample ID: Q2473-04 Matrix: SOIL

% Solid: 90.7

Q2473

SDG No.:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	11.3	Н	1	0	0	pН		07/02/25 10:30	9045D
Cyanide	0.25	J	1	0.046	0.27	mg/Kg	07/02/25 08:30	07/02/25 11:48	9012B
Ignitability	NO		1	0	0	oC		07/02/25 09:25	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.050	mg/Kg	07/01/25 14:35	07/02/25 10:27	9012B
Reactive Sulfide	6.37	J	1	0.20	10.0	mg/Kg	07/03/25 14:00	07/03/25 16:39	9034

Comments: pH result reported at temperature 23.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits