



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: Environmental Restoration, LLC

SDG No.: Q2481

Project: CC2-16 Analytical

RunNo.: LB136367

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV pH	pH	7.02	7	100	90-110	07/03/2025
Sample ID: CCV1 pH	pH	2.01	2.00	101	90-110	07/03/2025
Sample ID: CCV2 pH	pH	12.02	12.00	100	90-110	07/03/2025
Sample ID: CCV3 pH	pH	2.01	2.00	101	90-110	07/03/2025

Initial and Continuing Calibration Verification

Client: Environmental Restoration, LLC

SDG No.: Q2481

Project: CC2-16 Analytical

RunNo.: LB136395

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV						
Flash Point	o F	82.4	81	102	78-84	07/08/2025

Initial and Continuing Calibration Verification

Client: Environmental Restoration, LLC

SDG No.: Q2481

Project: CC2-16 Analytical

RunNo.: LB136398

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV						
Flash Point	o F	82.1	81	101	78-84	07/08/2025