

metals
- 14 -
ANALYSIS RUN LOG

Client: Environmental Restoration, LLC

Contract: ENVI60

Lab code: ACE

Sdg no.: Q2481

Instrument id number: _____ **Method:** _____

Run number: LB136391

Start date: 07/08/2025 **End date:** 07/08/2025

Lab sample id.	Client Sample Id	d/f	Time	Parameter list
S0	S0	1	0835	HG
S0.2	S0.2	1	0837	HG
S2.5	S2.5	1	0839	HG
S5	S5	1	0842	HG
S7.5	S7.5	1	0844	HG
S10	S10	1	0852	HG
ICV19	ICV19	1	0859	HG
ICB19	ICB19	1	0904	HG
CCV61	CCV61	1	0907	HG
CCB61	CCB61	1	0912	HG
CRA	CRA	1	0914	HG
CCV62	CCV62	1	0944	HG
CCB62	CCB62	1	0950	HG
PB168742BL	PB168742BL	1	1012	HG
PB168742BS	PB168742BS	1	1015	HG
Q2481-01	CC0627-AL	1	1017	HG
Q2481-01DUP	CC0627-ALDUP	1	1019	HG
Q2481-01MS	CC0627-ALMS	1	1021	HG
CCV63	CCV63	1	1024	HG
CCB63	CCB63	1	1026	HG
Q2481-01MSD	CC0627-ALMSD	1	1028	HG
Q2481-02	CC0627-CLOXPL	10	1032	HG
Q2481-03	CC0625-OXBL	10	1034	HG
Q2481-04	CC0627-AOXL	10	1037	HG
Q2481-05	CC0625-NL	1	1039	HG
Q2481-06	CC0267-OXPL	10	1042	HG
Q2481-07	CC0627-OXL	10	1044	HG
Q2481-08	CC0627-CLOXAL	1	1046	HG
Q2481-09	CC0627-BL	10	1049	HG
Q2481-10	CC0627-SFBL	1	1051	HG
CCV64	CCV64	1	1053	HG
CCB64	CCB64	1	1056	HG
PB168705TB	PB168705TB	1	1103	HG
Q2481-01L	CC0627-ALL	5	1110	HG
CCV65	CCV65	1	1114	HG
CCB65	CCB65	1	1117	HG

metals
- 14 -
ANALYSIS RUN LOG

Client: Environmental Restoration, LLC

Contract: ENVI60

Lab code: ACE

Sdg no.: Q2481

Instrument id number: _____ **Method:** _____

Run number: LB136434

Start date: 07/10/2025 **End date:** 07/11/2025

Lab sample id.	Client Sample Id	d/f	Time	Parameter list
S0	S0	1	1646	Ag,As,Ba,Cd,Cr,Pb,Se
S1	S1	1	1650	Ag,As,Ba,Cd,Cr,Pb,Se
S2	S2	1	1655	Ag,As,Ba,Cd,Cr,Pb,Se
S3	S3	1	1659	Ag,As,Ba,Cd,Cr,Pb,Se
S4	S4	1	1703	Ag,As,Ba,Cd,Cr,Pb,Se
S5	S5	1	1707	Ag,As,Ba,Cd,Cr,Pb,Se
ICV01	ICV01	1	1839	Ag,As,Ba,Cd,Cr,Pb,Se
LLICV01	LLICV01	1	1851	Ag,As,Ba,Cd,Cr,Pb,Se
ICB01	ICB01	1	1855	Ag,As,Ba,Cd,Cr,Pb,Se
CRI01	CRI01	1	1901	Ag,As,Ba,Cd,Cr,Pb,Se
ICSA01	ICSA01	1	1911	Ag,As,Ba,Cd,Cr,Pb,Se
ICSAB01	ICSAB01	1	1915	Ag,As,Ba,Cd,Cr,Pb,Se
CCV01	CCV01	1	1943	Ag,As,Ba,Cd,Cr,Pb,Se
CCB01	CCB01	1	1954	Ag,As,Ba,Cd,Cr,Pb,Se
CCV02	CCV02	1	2059	Ag,As,Ba,Cd,Cr,Pb,Se
CCB02	CCB02	1	2104	Ag,As,Ba,Cd,Cr,Pb,Se
PB168705TB	PB168705TB	1	2207	Ag,As,Ba,Cd,Cr,Pb,Se
CCV03	CCV03	1	2232	Ag,As,Ba,Cd,Cr,Pb,Se
CCB03	CCB03	1	2236	Ag,As,Ba,Cd,Cr,Pb,Se
CCV04	CCV04	1	2329	Ag,As,Ba,Cd,Cr,Pb,Se
CCB04	CCB04	1	2353	Ag,As,Ba,Cd,Cr,Pb,Se
PB168712BL	PB168712BL	1	0025	Ag,As,Ba,Cd,Cr,Pb,Se
PB168712BS	PB168712BS	1	0030	Ag,As,Ba,Cd,Cr,Pb,Se
CCV05	CCV05	1	0047	Ag,As,Ba,Cd,Cr,Pb,Se
CCB05	CCB05	1	0051	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-01	CC0627-AL	10	0104	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-01DUP	CC0627-ALDUP	10	0109	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-01L	CC0627-ALL	50	0114	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-01MS	CC0627-ALMS	10	0119	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-01MSD	CC0627-ALMSD	10	0124	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-02	CC0627-CLOXPL	10	0134	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-03	CC0625-OXBL	10	0139	Ag,As,Ba,Cd,Cr,Pb,Se
CCV06	CCV06	1	0147	Ag,As,Ba,Cd,Cr,Pb,Se
CCB06	CCB06	1	0223	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-04	CC0627-AOXL	5	0227	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-05	CC0625-NL	5	0232	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-06	CC0267-OXPL	5	0236	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-07	CC0627-OXL	5	0241	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-08	CC0627-CLOXAL	1	0245	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-09	CC0627-BL	10	0250	Ag,As,Ba,Cd,Cr,Pb,Se
Q2481-10	CC0627-SFBL	5	0255	Ag,As,Ba,Cd,Cr,Pb,Se

metals
- 14 -
ANALYSIS RUN LOG

Client: Environmental Restoration, LLC

Contract: ENVI60

Lab code: ACE

Sdg no.: Q2481

Instrument id number: _____

Method: _____

Run number: LB136434

Start date: 07/10/2025

End date: 07/11/2025

Lab sample id.	Client Sample Id	d/f	Time	Parameter list
CCV07	CCV07	1	0317	Ag,As,Ba,Cd,Cr,Pb,Se
CCB07	CCB07	1	0326	Ag,As,Ba,Cd,Cr,Pb,Se
CCV08	CCV08	1	0418	Ag,As,Ba,Cd,Cr,Pb,Se
CCB08	CCB08	1	0427	Ag,As,Ba,Cd,Cr,Pb,Se
CCV09	CCV09	1	0519	Ag,As,Ba,Cd,Cr,Pb,Se
CCB09	CCB09	1	0524	Ag,As,Ba,Cd,Cr,Pb,Se
CCV10	CCV10	1	0616	Ag,As,Ba,Cd,Cr,Pb,Se
CCB10	CCB10	1	0621	Ag,As,Ba,Cd,Cr,Pb,Se
CCV11	CCV11	1	0643	Ag,As,Ba,Cd,Cr,Pb,Se
CCB11	CCB11	1	0647	Ag,As,Ba,Cd,Cr,Pb,Se