

Surrogate Summary

SDG No.: Q2481

Client: Environmental Restoration, LLC

Analytical Method: 8151A

Lab Sample ID	Client ID	Parameter	Column	Spike	Result	Recovery(%)	Qual	Limits(%)	
								Low	High
I.BLK-PS031156.D	PIBLK-PS031156.D	2,4-DCAA	1	500	397	79		61	136
		2,4-DCAA	2	500	504	101		61	136
I.BLK-PS031232.D	PIBLK-PS031232.D	2,4-DCAA	1	500	412	82		61	136
		2,4-DCAA	2	500	491	98		61	136
Q2641-02MS	P001-CONCRETE001-01MS	2,4-DCAA	1	500	452	90		61	136
		2,4-DCAA	2	500	499	100		61	136
Q2641-02MSD	P001-CONCRETE001-01MSD	2,4-DCAA	1	500	418	84		61	136
		2,4-DCAA	2	500	463	93		61	136
PB169001BL	PB169001BL	2,4-DCAA	1	500	407	81		61	136
		2,4-DCAA	2	500	473	95		61	136
PB169001BS	PB169001BS	2,4-DCAA	1	500	488	98		61	136
		2,4-DCAA	2	500	501	100		61	136
PB168969TB	PB168969TB	2,4-DCAA	1	500	564	113		61	136
		2,4-DCAA	2	500	495	99		61	136
I.BLK-PS031242.D	PIBLK-PS031242.D	2,4-DCAA	1	500	422	84		61	136
		2,4-DCAA	2	500	498	100		61	136
Q2481-15	CC0627-AOXL	2,4-DCAA	1	500	398	80		61	136
		2,4-DCAA	2	500	554	111		61	136
Q2481-19	CC0627-CLOXAL	2,4-DCAA	1	500	504	101		61	136
		2,4-DCAA	2	500	377	75		61	136
Q2481-21	CC0627-SFBL	2,4-DCAA	1	500	642	128		61	136
		2,4-DCAA	2	500	434	87		61	136
I.BLK-PS031251.D	PIBLK-PS031251.D	2,4-DCAA	1	500	374	75		61	136
		2,4-DCAA	2	500	470	94		61	136
Q2481-13	CC0627-CLOXPL	2,4-DCAA	1	500	246	49	*	61	136
		2,4-DCAA	2	500	543	109		61	136
Q2481-14	CC0625-OBXL	2,4-DCAA	1	500	1260	252	*	61	136
		2,4-DCAA	2	500	860	172	*	61	136
Q2481-16	CC0625-NL	2,4-DCAA	1	500	184	37	*	61	136
		2,4-DCAA	2	500	2260	453	*	61	136
Q2481-17	CC0267-OBXL	2,4-DCAA	1	500	33.1	7	*	61	136
		2,4-DCAA	2	500	1270	254	*	61	136
Q2481-20	CC0627-BL	2,4-DCAA	1	500	507	101		61	136
		2,4-DCAA	2	500	3130	626	*	61	136
I.BLK-PS031259.D	PIBLK-PS031259.D	2,4-DCAA	1	500	171	34	*	61	136
		2,4-DCAA	2	500	34.5	7	*	61	136
I.BLK-PS031274.D	PIBLK-PS031274.D	2,4-DCAA	1	500	404	81		61	136
		2,4-DCAA	2	500	491	98		61	136
I.BLK-PS031315.D	PIBLK-PS031315.D	2,4-DCAA	1	500	431	86		61	136
		2,4-DCAA	2	500	499	100		61	136
Q2481-12	CC0627-AL	2,4-DCAA	1	500	399	80		61	136

Surrogate Summary

SDG No.: Q2481

Client: Environmental Restoration, LLC

Analytical Method: 8151A

Lab Sample ID	Client ID	Parameter	Column	Spike	Result	Recovery(%)	Qual	Limits(%)	
								Low	High
Q2481-12	CC0627-AL	2,4-DCAA	2	500	446	89		61	136
Q2481-18	CC0627-OXL	2,4-DCAA	1	500	10800	2153	*	61	136
		2,4-DCAA	2	500	580	116		61	136
I.BLK-PS031320.D	PIBLK-PS031320.D	2,4-DCAA	1	500	424	85		61	136
		2,4-DCAA	2	500	473	95		61	136