

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Walsh Construction Company II, LLC Date Collected: 07/01/25 11:10 Project: Construction of Shafts 17B-18B - PN 220084 Date Received: 07/01/25 Client Sample ID: G4(6-12)DL SDG No.: Q2487 Lab Sample ID: Q2487-10DL Matrix: SOIL % Solid: 72.6

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	t) Prep Date	Date Ana.	Ana Met.
TKN	1910	D	10	124	331	mg/Kg	07/07/25 10:45	07/09/25 13:32	SM4500-N Org C-21 plus NH3 B plus G-21

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits