

LAB CHRONICLE

OrderID:	Q2487	OrderDate:	7/2/2025 10:05:00 AM
Client:	Walsh Construction Company II, LLC	Project:	Construction of Shafts 17B-18B - PN 220084
Contact:	Jesse A. Sylvestri	Location:	A22,A53,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2487-01	G4(1.5)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/03/25	07/01/25
Q2487-02	G4(10)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/03/25	07/01/25
Q2487-03	G3(9)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/03/25	07/01/25
Q2487-04	G3(3)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/03/25	07/01/25
Q2487-05	G2(2.5)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/02/25	07/01/25
Q2487-05RE	G2(2.5)RE	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/03/25	07/01/25
Q2487-06	G2(9)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/03/25	07/01/25
Q2487-07	G1(4.5)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/03/25	07/01/25
Q2487-07RE	G1(4.5)RE	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/07/25	07/01/25
Q2487-08	G1(10)	SOIL	VOC-TCLVOA-10	8260D	07/01/25		07/07/25	07/01/25
Q2487-17	G4(1.5)	TCLP	TCLP VOA	8260D	07/01/25		07/03/25	07/01/25
Q2487-18	G4(10)	TCLP			07/01/25			07/01/25

LAB CHRONICLE

Q2487-19	G3(9)	TCLP	TCLP VOA	8260D		07/03/25
					07/01/25	07/01/25
Q2487-20	G3(3)	TCLP	TCLP VOA	8260D		07/03/25
					07/01/25	07/01/25
Q2487-21	G2(2.5)	TCLP	TCLP VOA	8260D		07/07/25
					07/01/25	07/01/25
Q2487-22	G2(9)	TCLP	TCLP VOA	8260D		07/07/25
					07/01/25	07/01/25
Q2487-23	G1(10)	TCLP	TCLP VOA	8260D		07/07/25
					07/01/25	07/01/25
Q2487-24	G1(4.5)	TCLP	TCLP VOA	8260D		07/07/25
					07/01/25	07/01/25
