

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G3(6-12)	SDG No.:	Q2489
Lab Sample ID:	Q2489-04	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-39-3	Barium	1100	N	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-43-9	Cadmium	2.50	U	1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7439-92-1	Lead	447	N	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7439-97-6	Mercury	1.06	J	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:14	7470A	
7782-49-2	Selenium	51.5	J	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits