



A
B
C
D

Order ID: Q2489

Project ID: Construction of Shafts 17B-18B - PN 22008

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID :	G4(0-6)							
Q2489-01	G4(0-6)	TCLP	Barium	329	J	72.8	500	ug/L
Q2489-01	G4(0-6)	TCLP	Cadmium	12.1	J	2.50	30.0	ug/L
Q2489-01	G4(0-6)	TCLP	Chromium	49.4	J	10.6	50.0	ug/L
Q2489-01	G4(0-6)	TCLP	Lead	588		11.5	60.0	ug/L
Q2489-01	G4(0-6)	TCLP	Selenium	57.6	J	48.2	100	ug/L
Client ID :	G4(6-12)							
Q2489-02	G4(6-12)	TCLP	Barium	1160		72.8	500	ug/L
Q2489-02	G4(6-12)	TCLP	Lead	136		11.5	60.0	ug/L
Q2489-02	G4(6-12)	TCLP	Mercury	1.16	J	0.76	2.00	ug/L
Q2489-02	G4(6-12)	TCLP	Selenium	49.9	J	48.2	100	ug/L
Client ID :	G3(0-6)							
Q2489-03	G3(0-6)	TCLP	Barium	267	J	72.8	500	ug/L
Q2489-03	G3(0-6)	TCLP	Cadmium	19.0	J	2.50	30.0	ug/L
Q2489-03	G3(0-6)	TCLP	Lead	1740		11.5	60.0	ug/L
Q2489-03	G3(0-6)	TCLP	Selenium	49.8	J	48.2	100	ug/L
Client ID :	G3(6-12)							
Q2489-04	G3(6-12)	TCLP	Barium	1100		72.8	500	ug/L
Q2489-04	G3(6-12)	TCLP	Lead	447		11.5	60.0	ug/L
Q2489-04	G3(6-12)	TCLP	Mercury	1.06	J	0.76	2.00	ug/L
Q2489-04	G3(6-12)	TCLP	Selenium	51.5	J	48.2	100	ug/L
Client ID :	G2(0-6)							
Q2489-05	G2(0-6)	TCLP	Barium	841		72.8	500	ug/L
Q2489-05	G2(0-6)	TCLP	Cadmium	12.8	J	2.50	30.0	ug/L
Q2489-05	G2(0-6)	TCLP	Lead	492		11.5	60.0	ug/L
Q2489-05	G2(0-6)	TCLP	Selenium	63.3	J	48.2	100	ug/L
Client ID :	G2(6-12)							
Q2489-06	G2(6-12)	TCLP	Barium	1420		72.8	500	ug/L
Q2489-06	G2(6-12)	TCLP	Mercury	1.63	J	0.76	2.00	ug/L
Client ID :	G1(0-6)							
Q2489-07	G1(0-6)	TCLP	Barium	884		72.8	500	ug/L
Q2489-07	G1(0-6)	TCLP	Cadmium	40.5		2.50	30.0	ug/L
Q2489-07	G1(0-6)	TCLP	Lead	721		11.5	60.0	ug/L
Client ID :	G1(6-12)							

Hit Summary Sheet
SW-846

SDG No.: Q2489

Order ID: Q2489

Client: Walsh Construction Company II, LLC

Project ID: Construction of Shafts 17B-18B - PN 2200

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Q2489-08	G1(6-12)	TCLP	Barium	3170		72.8	500	ug/L
Q2489-08	G1(6-12)	TCLP	Mercury	1.62	J	0.76	2.00	ug/L



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G4(0-6)	SDG No.:	Q2489
Lab Sample ID:	Q2489-01	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 22:40	6010D	SW3050
7440-39-3	Barium	329	JN	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 22:40	6010D	SW3050
7440-43-9	Cadmium	12.1	J	1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 22:40	6010D	SW3050
7440-47-3	Chromium	49.4	J	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 22:40	6010D	SW3050
7439-92-1	Lead	588	N	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 22:40	6010D	SW3050
7439-97-6	Mercury	0.76	U	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:04	7470A	
7782-49-2	Selenium	57.6	J	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 22:40	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 22:40	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G4(6-12)	SDG No.:	Q2489
Lab Sample ID:	Q2489-02	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 22:45	6010D	SW3050
7440-39-3	Barium	1160	N	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 22:45	6010D	SW3050
7440-43-9	Cadmium	2.50	U	1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 22:45	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 22:45	6010D	SW3050
7439-92-1	Lead	136	N	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 22:45	6010D	SW3050
7439-97-6	Mercury	1.16	J	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:06	7470A	
7782-49-2	Selenium	49.9	J	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 22:45	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 22:45	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G3(0-6)	SDG No.:	Q2489
Lab Sample ID:	Q2489-03	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 22:49	6010D	SW3050
7440-39-3	Barium	267	JN	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 22:49	6010D	SW3050
7440-43-9	Cadmium	19.0	J	1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 22:49	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 22:49	6010D	SW3050
7439-92-1	Lead	1740	N	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 22:49	6010D	SW3050
7439-97-6	Mercury	0.76	U	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:09	7470A	
7782-49-2	Selenium	49.8	J	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 22:49	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 22:49	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G3(6-12)	SDG No.:	Q2489
Lab Sample ID:	Q2489-04	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-39-3	Barium	1100	N	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-43-9	Cadmium	2.50	U	1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7439-92-1	Lead	447	N	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7439-97-6	Mercury	1.06	J	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:14	7470A	
7782-49-2	Selenium	51.5	J	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 22:53	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G2(0-6)	SDG No.:	Q2489
Lab Sample ID:	Q2489-05	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 22:58	6010D	SW3050
7440-39-3	Barium	841	N	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 22:58	6010D	SW3050
7440-43-9	Cadmium	12.8	J	1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 22:58	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 22:58	6010D	SW3050
7439-92-1	Lead	492	N	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 22:58	6010D	SW3050
7439-97-6	Mercury	0.76	U	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:16	7470A	
7782-49-2	Selenium	63.3	J	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 22:58	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 22:58	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G2(6-12)	SDG No.:	Q2489
Lab Sample ID:	Q2489-06	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 23:02	6010D	SW3050
7440-39-3	Barium	1420	N	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 23:02	6010D	SW3050
7440-43-9	Cadmium	2.50	U	1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 23:02	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 23:02	6010D	SW3050
7439-92-1	Lead	11.5	UN	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 23:02	6010D	SW3050
7439-97-6	Mercury	1.63	J	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:23	7470A	
7782-49-2	Selenium	48.2	U	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 23:02	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 23:02	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G1(0-6)	SDG No.:	Q2489
Lab Sample ID:	Q2489-07	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/10/25 23:06	6010D	SW3050
7440-39-3	Barium	884	N	1	72.8	500	ug/L	07/07/25 12:30	07/10/25 23:06	6010D	SW3050
7440-43-9	Cadmium	40.5		1	2.50	30.0	ug/L	07/07/25 12:30	07/10/25 23:06	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/10/25 23:06	6010D	SW3050
7439-92-1	Lead	721	N	1	11.5	60.0	ug/L	07/07/25 12:30	07/10/25 23:06	6010D	SW3050
7439-97-6	Mercury	0.76	U	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:25	7470A	
7782-49-2	Selenium	48.2	U	1	48.2	100	ug/L	07/07/25 12:30	07/10/25 23:06	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/10/25 23:06	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	07/01/25
Project:	Construction of Shafts 17B-18B - PN 220084	Date Received:	07/01/25
Client Sample ID:	G1(6-12)	SDG No.:	Q2489
Lab Sample ID:	Q2489-08	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	07/07/25 12:30	07/16/25 15:13	6010D	SW3050
7440-39-3	Barium	3170	N	1	72.8	500	ug/L	07/07/25 12:30	07/16/25 15:13	6010D	SW3050
7440-43-9	Cadmium	2.50	U	1	2.50	30.0	ug/L	07/07/25 12:30	07/16/25 15:13	6010D	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	07/07/25 12:30	07/16/25 15:13	6010D	SW3050
7439-92-1	Lead	11.5	UN	1	11.5	60.0	ug/L	07/07/25 12:30	07/16/25 15:13	6010D	SW3050
7439-97-6	Mercury	1.62	J	1	0.76	2.00	ug/L	07/08/25 08:10	07/09/25 12:27	7470A	
7782-49-2	Selenium	48.2	U	1	48.2	100	ug/L	07/07/25 12:30	07/16/25 15:13	6010D	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	07/07/25 12:30	07/16/25 15:13	6010D	SW3050

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP-FULL			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	Q2489	OrderDate:	7/2/2025 11:52:00 AM
Client:	Walsh Construction Company II, LLC	Project:	Construction of Shafts 17B-18B - PN 220084
Contact:	Jesse A. Sylvestri	Location:	--Select--

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2489-01	G4(0-6)	TCLP			07/01/25			07/01/25
			TCLP ICP Metals	6010D		07/07/25	07/10/25	
			TCLP Mercury	7470A		07/08/25	07/09/25	
			SPLP ICP Metals	6010D		07/09/25	07/17/25	
			SPLP Mercury	7470A		07/10/25	07/11/25	
Q2489-02	G4(6-12)	TCLP			07/01/25			07/01/25
			TCLP ICP Metals	6010D		07/07/25	07/10/25	
			TCLP Mercury	7470A		07/08/25	07/09/25	
			SPLP ICP Metals	6010D		07/09/25	07/17/25	
			SPLP Mercury	7470A		07/10/25	07/11/25	
Q2489-03	G3(0-6)	TCLP			07/01/25			07/01/25
			TCLP ICP Metals	6010D		07/07/25	07/10/25	
			TCLP Mercury	7470A		07/08/25	07/09/25	
			SPLP ICP Metals	6010D		07/09/25	07/17/25	
			SPLP Mercury	7470A		07/10/25	07/11/25	
Q2489-04	G3(6-12)	TCLP			07/01/25			07/01/25
			TCLP ICP Metals	6010D		07/07/25	07/10/25	
			TCLP Mercury	7470A		07/08/25	07/09/25	
			SPLP ICP Metals	6010D		07/09/25	07/17/25	
			SPLP Mercury	7470A		07/10/25	07/11/25	
Q2489-05	G2(0-6)	TCLP			07/01/25			07/01/25
			TCLP ICP Metals	6010D		07/07/25	07/10/25	
			TCLP Mercury	7470A		07/08/25	07/09/25	
			SPLP ICP Metals	6010D		07/09/25	07/17/25	
			SPLP Mercury	7470A		07/10/25	07/11/25	
Q2489-06	G2(6-12)	TCLP			07/01/25			07/01/25
			TCLP ICP Metals	6010D		07/07/25	07/10/25	

LAB CHRONICLE

Q2489-07	G1(0-6)	TCLP	TCLP Mercury	7470A	07/08/25	07/09/25	07/01/25	07/01/25
			SPLP ICP Metals	6010D	07/09/25	07/17/25		
			SPLP Mercury	7470A	07/10/25	07/11/25		
Q2489-08	G1(6-12)	TCLP	TCLP ICP Metals	6010D	07/07/25	07/10/25	07/01/25	07/01/25
			TCLP Mercury	7470A	07/08/25	07/09/25		
			SPLP ICP Metals	6010D	07/09/25	07/17/25		
			SPLP Mercury	7470A	07/10/25	07/11/25		
			TCLP ICP Metals	6010D	07/07/25	07/16/25	07/01/25	07/01/25
			TCLP Mercury	7470A	07/08/25	07/09/25		
			SPLP ICP Metals	6010D	07/09/25	07/17/25		
			SPLP Mercury	7470A	07/10/25	07/11/25		