

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: ATG - AKRON LAB Date Collected: 06/14/25 02:35 Project: Date Received: PO 25061630 07/02/25 Client Sample ID: Basement bedroom-2 SDG No.: Q2496 Lab Sample ID: Q2496-08 Matrix: SOIL % Solid: 100

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units(Dry Weight) Prep Date	Date Ana.	Ana Met.
Cyanide	0.042 HU	1 0.042	0.25	mg/Kg 07/02/25 12:30	07/03/25 15:02	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits