

Report of Analysis

Client:	ATG - AKRON LAB	Date Collected:	06/13/25 12:00
Project:	PO 25061636	Date Received:	07/02/25
Client Sample ID:	LR SW rug corner	SDG No.:	Q2497
Lab Sample ID:	Q2497-18	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.068	HJ	1	0.040	0.24	mg/Kg	07/03/25 10:00	07/07/25 13:10	9012B

Comments: _____

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements
 H = Sample Analysis Out Of Hold Time

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits