

Instrument ID: KONELAB

Daily Analysis Runlog For Sequence/QC Batch ID # LB136384

Review By	rubina	Review On	7/8/2025 1:11:23 PM
Supervise By	Iwona	Supervise On	7/8/2025 1:14:31 PM
SubDirectory	LB136384	Test	Cyanide
STD. NAME	STD REF.#		
ICAL Standard	WP113823,WP113824,WP113825,WP113826,WP113827,WP113828,WP113829		
ICV Standard	W3012		
CCV Standard	WP113824		
ICSA Standard	N/A		
CRI Standard	N/A		
LCS Standard	WP112995		
Chk Standard	WP112643,WP112900,WP113831		

Sr#	SampleId	ClientID	QcType	Date	Comment	Operator	Status
1	0.0PPBCN	0.0PPBCN	CAL1	07/07/25 10:39		rubina	OK
2	5.0PPBCN	5.0PPBCN	CAL2	07/07/25 10:39		rubina	OK
3	10PPBCN	10PPBCN	CAL3	07/07/25 10:39		rubina	OK
4	50PPBCN	50PPBCN	CAL4	07/07/25 10:39		rubina	OK
5	100PPBCN	100PPBCN	CAL5	07/07/25 10:39		rubina	OK
6	250PPBCN	250PPBCN	CAL6	07/07/25 10:39		rubina	OK
7	500PPBCN	500PPBCN	CAL7	07/07/25 10:39		rubina	OK
8	ICV1	ICV1	ICV	07/07/25 12:32		rubina	OK
9	ICB1	ICB1	ICB	07/07/25 12:32		rubina	OK
10	CCV1	CCV1	CCV	07/07/25 12:32		rubina	OK
11	CCB1	CCB1	CCB	07/07/25 12:32		rubina	OK
12	PB168730BL	PB168730BL	MB	07/07/25 12:32		rubina	OK
13	PB168730BS	PB168730BS	LCS	07/07/25 12:39		rubina	OK
14	LOWPB168730	LOWPB168730	SAM	07/07/25 12:39		rubina	OK
15	HIGHPB168730	HIGHPB168730	SAM	07/07/25 12:39		rubina	OK
16	Q2494-01	Playhouse/Storag	SAM	07/07/25 12:39		rubina	OK
17	Q2494-02	Playhouse/Storag	SAM	07/07/25 12:40		rubina	OK
18	Q2494-03	Garage Seat Foa	SAM	07/07/25 12:40		rubina	OK

Instrument ID: KONELAB

Daily Analysis Runlog For Sequence/QC Batch ID # LB136384

Review By	rubina	Review On	7/8/2025 1:11:23 PM
Supervise By	Iwona	Supervise On	7/8/2025 1:14:31 PM
SubDirectory	LB136384	Test	Cyanide
STD. NAME	STD REF.#		
ICAL Standard	WP113823,WP113824,WP113825,WP113826,WP113827,WP113828,WP113829		
ICV Standard	W3012		
CCV Standard	WP113824		
ICSA Standard	N/A		
CRI Standard	N/A		
LCS Standard	WP112995		
Chk Standard	WP112643,WP112900,WP113831		

19	Q2494-04	Black foam in Sou	SAM	07/07/25 12:40		rubina	OK
20	Q2494-05	Kids Room styof	SAM	07/07/25 12:40		rubina	OK
21	Q2494-06	Kids Room Lower	SAM	07/07/25 12:40		rubina	OK
22	CCV2	CCV2	CCV	07/07/25 12:47		rubina	OK
23	CCB2	CCB2	CCB	07/07/25 12:47		rubina	OK
24	Q2494-07	Kids Room styof	SAM	07/07/25 12:47		rubina	OK
25	Q2494-08	Dog Beg Foam	SAM	07/07/25 12:47		rubina	OK
26	Q2494-09	Cotton Layer - Ott	SAM	07/07/25 12:47		rubina	OK
27	Q2494-10	Foam Ottoman	SAM	07/07/25 12:47		rubina	OK
28	Q2494-11	Foyer North Wall	SAM	07/07/25 12:47		rubina	OK
29	Q2494-12	NE Stucco Exterio	SAM	07/07/25 12:47		rubina	OK
30	Q2494-13	Master Mattress	SAM	07/07/25 12:47		rubina	OK
31	Q2497-21	office east wall pl	SAM	07/07/25 12:47		rubina	OK
32	Q2497-22	Bedroom north w	SAM	07/07/25 12:47		rubina	OK
33	Q2497-23	Kitchen ceiling pl	SAM	07/07/25 12:55		rubina	OK
34	CCV3	CCV3	CCV	07/07/25 12:55		rubina	OK
35	CCB3	CCB3	CCB	07/07/25 12:55		rubina	OK
36	Q2498-01	NE Bd bed foam	SAM	07/07/25 12:55		rubina	OK
37	Q2498-02	NE Bd pillow foa	SAM	07/07/25 12:55		rubina	OK
38	Q2498-03	Master bed NE m	SAM	07/07/25 12:55		rubina	OK

Instrument ID: KONELAB

Daily Analysis Runlog For Sequence/QC Batch ID # LB136384

Review By	rubina	Review On	7/8/2025 1:11:23 PM
Supervise By	Iwona	Supervise On	7/8/2025 1:14:31 PM
SubDirectory	LB136384	Test	Cyanide
STD. NAME	STD REF.#		
ICAL Standard	WP113823,WP113824,WP113825,WP113826,WP113827,WP113828,WP113829		
ICV Standard	W3012		
CCV Standard	WP113824		
ICSA Standard	N/A		
CRI Standard	N/A		
LCS Standard	WP112995		
Chk Standard	WP112643,WP112900,WP113831		

39	Q2498-03DUP	Master bed NE mDUP	DUP	07/07/25 12:55		rubina	OK
40	Q2498-03MS	Master bed NE mMS	MS	07/07/25 12:55		rubina	OK
41	Q2498-03MSD	Master bed NE mMSD	MSD	07/07/25 12:55		rubina	OK
42	PB168729BS	PB168729BS	LCS	07/07/25 12:55		rubina	OK
43	Q2497-01	SW bedroom (San	SAM	07/07/25 12:55		rubina	OK
44	Q2497-02	Salman s room SE	SAM	07/07/25 13:02		rubina	OK
45	Q2497-03	Sanah s room bed	SAM	07/07/25 13:02		rubina	OK
46	CCV4	CCV4	CCV	07/07/25 13:02		rubina	OK
47	CCB4	CCB4	CCB	07/07/25 13:02		rubina	OK
48	Q2497-04	Salman s room m	SAM	07/07/25 13:02		rubina	OK
49	Q2497-05	Master bed mattr	SAM	07/07/25 13:02		rubina	OK
50	Q2497-06	Kaihaan s room m	SAM	07/07/25 13:02		rubina	OK
51	Q2497-07	Garage foam yog	SAM	07/07/25 13:02		rubina	OK
52	Q2497-08	Living room west	SAM	07/07/25 13:02		rubina	OK
53	Q2497-09	Entrance rug	SAM	07/07/25 13:02		rubina	OK
54	Q2497-10	south exterior re	SAM	07/07/25 13:02		rubina	OK
55	Q2497-11	Garage gym floor	SAM	07/07/25 13:10		rubina	OK
56	Q2497-12	Rug by the back d	SAM	07/07/25 13:10		rubina	OK
57	Q2497-13	Guest bed mattre	SAM	07/07/25 13:10		rubina	OK
58	CCV5	CCV5	CCV	07/07/25 13:10		rubina	OK

Instrument ID: KONELAB

Daily Analysis Runlog For Sequence/QC Batch ID # LB136384

Review By	rubina	Review On	7/8/2025 1:11:23 PM
Supervise By	Iwona	Supervise On	7/8/2025 1:14:31 PM
SubDirectory	LB136384	Test	Cyanide
STD. NAME	STD REF.#		
ICAL Standard	WP113823,WP113824,WP113825,WP113826,WP113827,WP113828,WP113829		
ICV Standard	W3012		
CCV Standard	WP113824		
ICSA Standard	N/A		
CRI Standard	N/A		
LCS Standard	WP112995		
Chk Standard	WP112643,WP112900,WP113831		

59	CCB5	CCB5	CCB	07/07/25 13:10		rubina	OK
60	Q2497-14	Garage backyard	SAM	07/07/25 13:10		rubina	OK
61	Q2497-15	LR SW conner chai	SAM	07/07/25 13:10		rubina	OK
62	Q2497-16	Living room NE co	SAM	07/07/25 13:10		rubina	OK
63	Q2497-17	Dining room SW c	SAM	07/07/25 13:10		rubina	OK
64	Q2497-18	LR SW rug corner	SAM	07/07/25 13:10		rubina	OK
65	Q2497-19	LR west wall plug	SAM	07/07/25 13:10		rubina	OK
66	Q2497-20	LR NE corner plug	SAM	07/07/25 13:17		rubina	OK
67	Q2497-20DUP	LR NE corner plugDU	DUP	07/07/25 13:17		rubina	OK
68	Q2497-20MS	LR NE corner plugMS	MS	07/07/25 13:17		rubina	OK
69	Q2497-20MSD	LR NE corner plugMS	MSD	07/07/25 13:17		rubina	OK
70	CCV6	CCV6	CCV	07/07/25 13:17		rubina	OK
71	CCB6	CCB6	CCB	07/07/25 13:17		rubina	OK
72	PB168729BL	PB168729BL	MB	07/07/25 13:17		rubina	OK
73	CCV7	CCV7	CCV	07/07/25 13:17		rubina	OK
74	CCB7	CCB7	CCB	07/07/25 13:20		rubina	OK