

Report of Analysis

Client:	VERINA CONSULTING GROUP, LLC	Date Collected:	07/03/25 10:10
Project:	Rotor Clip NJ WTD - 2025	Date Received:	07/03/25
Client Sample ID:	WATER-TREATMENT DISCHARGEDL	SDG No.:	Q2512
Lab Sample ID:	Q2512-01DL	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	2.40	D	2	0.060	0.20	mg/L	07/08/25 15:50	07/09/25 11:04	SM 4500-NH3 B plus G-21

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits