

LAB CHRONICLE

OrderID:	Q2514	OrderDate:	7/3/2025 1:29:00 PM
Client:	CDM Smith	Project:	South River WM Replacement
Contact:	Marcie Ann Encinas	Location:	O21,O22,VOA Lab

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2514-01	TP-92	SOIL			07/02/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-02	TP-93	SOIL			07/02/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-03	TP-94	SOIL			07/02/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-04	TP-96	SOIL			07/02/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-05	TP-97	SOIL			07/02/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-06	TP-103	SOIL			07/02/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-07	TP-36	SOIL			07/03/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-08	TP-78	SOIL			07/03/25			07/03/25
			PCB	8082A		07/07/25	07/08/25	
			Pesticide-TCL	8081B		07/07/25	07/07/25	
Q2514-09	TP-81	SOIL			07/03/25			07/03/25

LAB CHRONICLE

Q2514-10	TP-90	SOIL	PCB	8082A		07/07/25	07/08/25
			Pesticide-TCL	8081B		07/07/25	07/07/25
					07/03/25		
							07/03/25
			PCB	8082A		07/07/25	07/08/25
			Pesticide-TCL	8081B		07/07/25	07/07/25
