



A

B

C

SAMPLE DATA

Report of Analysis

Client:	Major Products	Date Collected:	07/08/25 11:30
Project:	Floor Drain Water 2025	Date Received:	07/08/25
Client Sample ID:	DRAIN-WATER-TANK-1	SDG No.:	Q2522
Lab Sample ID:	Q2522-01	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	8030		1	0.20	2.00	mg/L		07/09/25 16:40	SM 5210 B-16
TSS	495		1	1.00	4.00	mg/L		07/10/25 10:00	SM 2540 D-20

Comments:

U = Not Detected
LOQ = Limit of Quantitation
MDL = Method Detection Limit
LOD = Limit of Detection
D = Dilution
Q = indicates LCS control criteria did not meet requirements
H = Sample Analysis Out Of Hold Time

J = Estimated Value
B = Analyte Found in Associated Method Blank
* = indicates the duplicate analysis is not within control limits.
E = Indicates the reported value is estimated because of the presence of interference.
OR = Over Range
N =Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	Q2522	OrderDate:	7/8/2025 12:33:00 PM
Client:	Major Products	Project:	Floor Drain Water 2025
Contact:	Paul Bustamante	Location:	O11

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2522-01	DRAIN-WATER-TANK-1	WATER			07/08/25 11:30			07/08/25
			BOD5	SM5210 B			07/09/25 16:40	
			TSS	SM2540 D			07/10/25 10:00	