

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 07/10/25 08:30 Project: Hadley Road Date Received: 07/10/25 Client Sample ID: RT3997 SDG No.: Q2556 Lab Sample ID: Q2556-01 Matrix: SOIL % Solid: 87

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ignitability	NO		1	0	0	oC		07/11/25 08:35	1030
pН	11.5	Н	1	0	0	pН		07/11/25 09:20	9045D
Reactive Cyanide	0.050	U	1	0.0084	0.050	mg/Kg	07/11/25 08:45	07/11/25 12:58	9012B
Reactive Sulfide	4.79	J	1	0.20	10.0	mg/Kg	07/11/25 12:45	07/11/25 15:17	9034

Comments: pH result reported at temperature 22.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits