

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Date Collected: 07/10/25 12:00

Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 07/10/25

Client Sample ID: WC-A2-14-C SDG No.: Q2579

Lab Sample ID: Q2579-07 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	11.9	Н	1	0	0	pН		07/11/25 15:45	9045D
Ignitability	NO		1	0	0	oC		07/14/25 09:22	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.050	mg/Kg	07/11/25 08:45	07/11/25 13:13	9012B
Reactive Sulfide	4.75	J	1	0.20	10.0	mg/Kg	07/11/25 12:45	07/11/25 15:49	9034

Comments: pH result reported at temperature 212 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits