



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: PARSONS Engineering of New York, Inc.

SDG No.: Q2592

Project: Con Edison - East River Site 2

RunNo.: LB136472

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
pH		pH	7.01	7	100	90-110	07/15/2025
Sample ID:	CCV1						
pH		pH	2.01	2.00	101	90-110	07/15/2025
Sample ID:	CCV2						
pH		pH	12.02	12.00	100	90-110	07/15/2025

Initial and Continuing Calibration Verification

Client: PARSONS Engineering of New York, Inc.

SDG No.: Q2592

Project: Con Edison - East River Site 2

RunNo.: LB136475

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
Corrosivity		pH	7.00	7	100	90-110	07/15/2025
Sample ID:	CCV1						
Corrosivity		pH	2.01	2.00	101	90-110	07/15/2025
Sample ID:	CCV2						
Corrosivity		pH	12.02	12.00	100	90-110	07/15/2025

Initial and Continuing Calibration Verification

Client: PARSONS Engineering of New York, Inc.

SDG No.: Q2592

Project: Con Edison - East River Site 2

RunNo.: LB136502

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.095	0.099	96	85-115	07/16/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	07/16/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	07/16/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	07/16/2025