

Report of Analysis

Client:	T&A Construction Inc	Date Collected:	07/14/25 13:00
Project:	Kingsland Point Park Water Main	Date Received:	07/14/25
Client Sample ID:	TRENCH	SDG No.:	Q2600
Lab Sample ID:	Q2600-01	Matrix:	SOIL
		% Solid:	75.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.076	J	1	0.053	0.32	mg/Kg	07/16/25 08:10	07/16/25 10:31	9012B
Hexavalent Chromium	0.092	U	1	0.092	0.53	mg/Kg	07/16/25 12:40	07/16/25 16:04	7196A
pH	7.55	H	1	0	0	pH		07/15/25 09:15	9045D

Comments: pH result reported at temperature 24.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits